




Tackling obsolescence issues for power electronics

Wim Platschorre

Early 1900

Holec Traction:

- virtually all trains in the Netherlands
- Class 323 (UK & Malaysia)
- Citadis / Regiocitadis



1999

Acquisition by
Alstom
(France)

2005

- Alstom moves development to France
- Engineering core (Traction Centre of Excellence) acquired by **Strukton Rail**

Strukton Rail:

- Turnover \$832 Mln. (2013)
- 3,400 employees

Strukton Rolling Stock:

- Turnover \$32 Mln. (2013)
- 120 employees

Train operators worries:

- 15 – 20 years ago: power electronics based on Gate Turn Off-thyristors
- Obsolescence of GTO's
- DC, or upgrade to AC? Costs analysis




Train operators worries:

- Control electronics: replace or rebuilt





Example GTO inverter 90's

- Only partial modular, shared components
- Critical fibre optic control





Example GTO inverter 90's







- All components on modules
- Module functionality independent
- Protection and diagnosis onboard every module













- di / dt and dV / dt control => optimized switching behaviour
- Zero dead band: turn-off and turn-on within one phaseleg simultaneously
- Fast short circuit detection





Chicago O'Hare airport shuttle

- DC motors not replaced
- New control electronics
- IGBT based DC Chopper
- Integrate existing brake control in new drive box



- DC motors re-used
- Control electronics updated, interface to new power electronics
- Battery charger also renewed





India, 6000 HP locomotive

- New build locomotives, but existing design, originally with GTOs.
- 4.5kV IGBTs
- Watercooled



- Replacement rotating converter for a static converter
- Power: 150kW
- Line voltage 3kV









- Obsolete IGBT Purchasing can a challenge
- Used and Counterfeit Problem
- Premature Failures due to Incorrect Gate Driver



→
Before
→




→
After
→





- New Gate Driver is required in order to update IGBT Model
- Maintain Same Drive Control Unit
- Fine tune switching behavior to improve IGBT Performance and Losses
- Implement new features and protection like IGBT Parameters Logging, Fast Type I short circuit protection and Enhanced Fiber Optic interface

Plug & Play Phase Inverter Update



↑ Before ↑

↓ After ↓



- Correct IGBT replacement procedure
- Busbar reengineering and/or redesign

Booth 1249

AMEPOWER

jmunoz@AmePower.com



Strukton
Rail

wim.platschorre@strukton.com

michel.stasse@strukton.com