## **Denver RTD's UAV Program**

#### Mike Nabhan

Denver RTD, DataOps Engineer
Denver, Colorado

## **Key Presentation Take-Aways**

- Any agency can do this
- It does not have to be expensive
- It can save your agency money
- It does not require initial expertise
- Benefits outside of safety

## **Agency Facts**

- 2342 Square Miles of Service Area
- 60 Miles of Light Rail
- 29 Miles of Commuter Rail
- 1023 Buses/172 LRVs
- 480 Million Dollar Operating Budget
- 2800 Employees

## **RTD UAV Program Facts**

- RTD is currently flying UAVs
- RTD did not use a consultant
- This program was an effort of three employees
- Program was started part-time in addition to regular responsibilities

# **Unmanned Aerial Vehicles, Not Drones**

- Internally Known as UAVs
- "Drones" has a certain connotation
- Security Functions are off limits
- Attempt to manage perception



#### **How We Did It**

- Initially applied for Section 333 exemption
  - Now deprecated
- Two Private Pilots on Staff
- Four Licensed aircraft mechanics on staff
- None of this is required now...more on this later




#### **New Rules**

- Must weight less than 55lbs
- Visual Line of Sight
- Cannot operate over people without a waiver
- Daylight only
- Visual observer optional
- Must yield to other aircraft

- Maximum speed of 100mph
- Maximum altitude of 400 feet above ground level
- 3 Miles visibility
- Operations are allowed in controlled airspace with permission
  - Now a website for getting this permission
- Most restrictions can be waived if you can demonstrate how to do it and still be safe


## **Program Costs/Savings**

- \$18,078.98
  - Over 60% of this cost was thermal camera
- \$95,000/YR in recurring labor cost savings
  - Faster inspections
  - Less worker-hours required



#### **Hardware Overview**

- All Commercial Off The Shelf
  - DJI Inspire
- Lower cost than specialized systems
- Easier to Train
- Community support
  - Open API
  - Dozens of 3<sup>rd</sup> Party Software
  - Informal support through web forums and user groups




## **DJI Inspire 1 Unmanned Aerial Vehicle**





## **Zenmuse Z3 Zoom Camera**





#### **Zenmuse XT Infrared Camera**





#### **Current Use Case and Benefits**

- Asset Inspections
  - SGR Rail Infrastructure
  - Facilities
- On-Demand Inspections
  - Non-standard at request of internal business group
- Utility Locates
- Marketing Films

- No need to hire outside firm for marketing videos
- Removes inspectors from hazardous situations
- Can perform visual inspections in less time, more simply (think bridges)
- No need for slow zones during rail inspections
  - Passengers no longer affected



Forecast Asset Replacement Intervals

Asset Deterioration

Autonomous Inspections

Computer Vision


## **Future Use Cases**


- Automated Inspections
- Computer Vision
- Emergency incident response



## **Computer Vision**

- People can identify mountains, computers cannot
- Google API
- Can be utilized to automatically identify specified elements in footage





## How you can do it

- You can:
  - Pilot program for <\$1,000</li>
  - Full Program for <\$20,000</li>
- Companies offer training for FAA Knowledge Test
- Companies offer technical training for flying
  - Likely unnecessary

#### To become a pilot you must:

- Be at least 16 years old
- Be able to read, speak, write, and understand English (exceptions may be made if the person is unable to meet one of these requirements for a medical reason, such as hearing impairment)
- Be in a physical and mental condition to safely operate a small UAS
- Pass the initial aeronautical knowledge exam at an FAA-approved knowledge testing center

#### Pilot certificate Requirements


- Must be easily accessible by the remote pilot during all UAS operations
- Valid for 2 years certificate holders must pass a recurrent knowledge test every two years

## **Water Damage**




**Boulder Bus Garage Roof** 








## **Emergency Response Training**





#### **Track Switch**




- Track switch identified as potentially malfunctioning by activating on warm day
- Not feasible to identify this sort of failure without physical presence on the alignment

## **Easy Property Survey**



# **Image Detail**



## **Questions?**

Feel free to call or email me

• Phone: 303-299-2282

• Email: mike.nabhan@rtd-denver.com